
## Pony Cooling Clamps V2.14

For rapid cool down of small printing tapes and belts.

- 2" x 3" cooling area
- 4" x 6" cooling area



Distributed By: